

ARTICULATED CRANE

EQUIPMENT ID: 0149F025

Make: Franna **Model:** MAC25 **Year:** 1999
Capacity: 25 tonne **Serial No.:** 25020
Engine No.: H07CTA43326 **Vin/Chassis:** _____

Engine Make: Hino
 Engine: No. of Cylinders: 6
 Carrier Kilometres: _____
 Crane Engine Hours: 5030
 Tyre size: 1400 20
 Tyre condition: Good
 Max. travel speed (km/h): 80
 Transmission Type: Auto X Semi Auto Manual
 Airconditioning: Yes X No
 Centre Pins Condition: Good (Assessed every year during Cranesafe inspection)
 Steering Pins Condition: Good (As above)
 Boom Pivot Pins Condition: Good (As above)
 Length of Main Boom (under hydraulic power): 14.32
 Fly Jib Type (fixed, swing around etc.): N/A
 Fly Jib Length: N/A
 Fitted with computerised lifting gauges: Yes X No
 Spreader Bar: Yes No X (Can supply separate on request)
 Rhino Hook: Yes X No
 Hook Blocks: (Hook block sizes - tonnage) Yes X No Sizes: Standard 25T
 Accessories: _____

DOCUMENTATION / CERTIFICATIONS

Manuals: _____ Operators: Yes X No Service: Yes No X Parts: Yes No X
 Queensland 10 year Inspection? Yes No X Expiry date: _____
 Aust. Standard 10 year Inspection? Yes X No Expiry date: March 2020
 Crane Safe Certified: Yes X No Expiry date: 27-04-2019
 Road registration: Yes No X Rego No.: _____ State: _____ Expiry date: _____

GENERAL:

Dimensions for transport/shipping: Weight (kg): _____ Overall length (mm): _____
 Width (mm): _____ Height (mm): _____
 Overall condition (panels, rust, etc): _____
 Painted Colours: _____

Please note: Hours & Kilometres are approximate.

For more information, contact:

Darren Woodley

Web Site: www.boomtrading.com.au Email: dwoodley@boomlogistics.com.au