

ARTICULATED CRANE

EQUIPMENT ID: 0548F020

Make: Franna **Model:** AT20 **Year:** 2001
Capacity: 20 tonne **Serial No.:** 3354
Engine No.: HO7CTA44377 **Vin/Chassis:** _____

Engine Make: Hino
 Engine: No. of Cylinders: 6
 Carrier Kilometres: _____
 Crane Engine Hours: 9242
 Tyre size: 1200 R20
 Tyre condition: Good
 Max. travel speed (km/h): 80
 Transmission Type: Auto X Semi Auto Manual
 Airconditioning: Yes X No
 Centre Pins Condition: Good (Assessed every year during Cranesafe inspection)
 Steering Pins Condition: Good (As above)
 Boom Pivot Pins Condition: Good (As above)
 Length of Main Boom (under hydraulic power): 13.85 ?
 Fly Jib Type (fixed, swing around etc.): N/A
 Fly Jib Length: N/A
 Fitted with computerised lifting gauges: Yes X No
 Spreader Bar: Yes No X (Can supply separate on request)
 Rhino Hook: Yes X No
 Hook Blocks: (Hook block sizes - tonnage) Yes X No Sizes: Standard 20T
 Accessories: _____

DOCUMENTATION / CERTIFICATIONS

Manuals: _____ Operators: Yes X No Service: Yes No X Parts: Yes No X
 Queensland 10 year Inspection? Yes No X Expiry date: _____
 Aust. Standard 10 year Inspection? Yes X No Expiry date: 2023
 Crane Safe Certified: Yes X No Expiry date: 10-12-2018
 Road registration: Yes X No Rego No.: CJ41PK State: NSW Expiry date: 27/11/2019

GENERAL:

Dimensions for transport/shipping: Weight (kg): _____ Overall length (mm): _____
 Width (mm): _____ Height (mm): _____
 Overall condition (panels, rust, etc): _____
 Painted Colours: _____

Please note: Hours & Kilometres are approximate.

For more information, contact:

Darren Woodley

Web Site: www.boomtrading.com.au Email: dwoodley@boomlogistics.com.au