

ARTICULATED CRANE**EQUIPMENT ID: 0601F020**

Make: Franna **Model:** AT20 **Year:** 2003
Capacity: 20 tonne **Serial No.:** 3409
Engine No.: OM906LA00301266 **Vin/Chassis:** _____

Engine Make: Mercedes
Engine: No. of Cylinders: 6
Carrier Kilometres: _____
Crane Engine Hours: 13416
Tyre size: 1200 R20
Tyre condition: Good
Max. travel speed (km/h): 80
Transmission Type: Auto X Semi Auto Manual
Airconditioning: Yes X No
Centre Pins Condition: Good (Assessed every year during Cranesafe inspection)
Steering Pins Condition: Good (As above)
Boom Pivot Pins Condition: Good (As above)
Length of Main Boom (under hydraulic power): 13.85 ?
Fly Jib Type (fixed, swing around etc.): N/A
Fly Jib Length: N/A
Fitted with computerised lifting gauges: Yes X No
Spreader Bar: Yes No X (Can supply separate on request)
Rhino Hook: Yes X No
Hook Blocks: (Hook block sizes - tonnage) Yes X No Sizes: Standard 20T
Accessories: _____

DOCUMENTATION / CERTIFICATIONS

Manuals: Operators: Yes X No Service: Yes No X Parts: Yes No X
Queensland 10 year Inspection? Yes No X Expiry date: _____
Aust. Standard 10 year Inspection? Yes X No Expiry date: 2019
Crane Safe Certified: Yes X No Expiry date: 02-06-2019
Road registration: Yes X No Rego No.: CJ82PJ State: NSW Expiry date: 30/08/2019

GENERAL:

Dimensions for transport/shipping: Weight (kg): _____ Overall length (mm): _____
Width (mm): _____ Height (mm): _____
Overall condition (panels, rust, etc): _____
Painted Colours: _____

Please note: Hours & Kilometres are approximate.

For more information, contact:**Darren Woodley**Web Site: www.boomtrading.com.au Email: dwoodley@boomlogistics.com.au